

# Project Sheet



## Checked Baggage Inspection System (CBIS) El Paso International Airport

### CLIENT

El Paso International Airport

### LOCATION

El Paso, TX

### ROLE

Construction Management

### COST/SIZE

\$24 Million

As part of a decades long relationship with El Paso International Airport, ECM was hired to manage the construction of the Checked Baggage Inspection System (CBIS). ECM provided full-time, on-site project and construction management including scope analysis, scheduling and constructability reviews. ECM also coordinated activities with Airport facilities, Operations & Maintenance, and Security and IT personnel.

The CBIS project involved the complete replacement of the existing baggage handling system with new equipment that provides for more effective and efficient operations. The work included the installation of a temporary check baggage inspection station and the construction of a new 30,000 SF single-story enclosed building that serves as the airport's baggage system with fully automated conveyor lines divided into three sections: check baggage inspection system, check baggage resolution area, and the baggage make-up unit. ECM also managed the interior remodel and renovation of office areas behind the Terminal Building's ticket counters, upgrades to existing ticket counter areas and improvements to airfield site entries and tuck courts.