



## National Guard Readiness Center Texas Military Department

### CLIENT

Texas Military Department

### LOCATION

El Paso, TX

### ROLE

Construction Inspections

### COST/SIZE

\$5.7 Million  
40,000 SF

The Texas National Guard building in northeast El Paso, TX was renovated as part of the statewide Texas Armory Revitalization Program to provide more energy-efficiency facilities. The improvements included abatement, demolition of internal walls, new geothermal system, painting, flooring, plumbing, fire protection system, and parking lot asphalt. The Center focuses on the training of the Army Reserve. Staff will train in preparation for border work, natural disasters, and relief scenarios.

ECM provided construction inspections for all aspects of the construction including the electrical, mechanical, civil, and plumbing improvements and served as the third-party inspector for payment applications. Coordination, documentation, and reporting of inspections with the owner and contractor were some of the deliverables