# **Project Sheet**



# Plan Review and Third Party Inspections Socorro Independent School

## **CLIENT**

Socorro Independent School District

#### LOCATION

El Paso, TX

#### ROLE

Plan Review Third Party Inspections

## **COST/SIZE**

\$16 Million 109,400 SF Socorro Independent School District enlisted ECM's assistance for plan review and third-party inspection services on the \$16 million Mission Ridge Elementary School. The 109,400 SF elementary school had 32 classrooms, two science labs, a media center, an amphitheater, a kitchen, a cafeteria, a gym, baseball courts, and track and soccer fields.

ECM's plan review and third-party inspections included a review of the building, mechanical, electrical, plumbing, landscaping drawings, and code compliance. Certified ICC inspectors made 270 inspections during the construction process.

ECM was also responsible to coordinate work with the contractor, district, and the emergency district to conform to the specific requirements of the different entities. Once all requirements were satisfied, ECM issued the "Certificate of Occupancy" which allowed the school district to use the new facility for its intended use.

El Paso Office 404 Executive Center Blvd. El Paso, TX 79902 915.351.1900

www.ecmintl.com www.jmt.com Austin Office 2211 SIH35, Ste. 200 Austin, TX 78741 512.667.7269

A JIVISION