



Property Condition Assessments El Paso Independent School District

CLIENT

El Paso Independent School
District

LOCATION

El Paso, TX

ROLE

Facilities Condition Assessments

COST/SIZE

8.3 Million SF

When the El Paso Independent School District prepared for a Bond Initiative they turned to a team that included ECM for assistance.

ECM conducted on-site evaluations of the District's facilities to determine each facility's effectiveness in terms of general conditions and suitability to serve the District's educational program. The appraisal identified infrastructure deficiencies and included a brief description of the required corrective action/repairs to bring the facilities up to current code and safety standards in order to extend the life of the buildings.

With nearly 8.3 million square feet, spread over more than 100 facilities, ECM was able to complete the assessments and share valuable information to their teaming partners to complete the analysis for general conditions, physical and operational deficiencies.